



# Manual for assembling a goniometer stand

1. Check completeness.



2. Attach and secure the crossbars with bolts.



3. Assemble the tabletop from two parts and secure with bolts.

